

FIG. 12




Fig. 1 is a schematic diagram of a mechanical assembly in a perspective view. The assembly includes a base 84, a central frame 80, and a top plate 83. A central shaft 81 is supported by bearings 82. A motor 62 is connected to the shaft. A dashed box 33 indicates a specific region. A coordinate system (X, Y, Z) is shown at the bottom right.